

Komatsu PC170 LC-11 | LIGHT DAMAGE | WORKING CONDITION

COMMON

ID	113820
Marque	Komatsu
Chassis	Grappe

PROPERTIES

Année de construction	2017
Heures de travail	5.731
Numéro d'identification véhicule	KMTPC26CHUF40013
Poids à vide	18.400 kg



ACCESSOIRES

- Radio / lecteur CD

DESCRIPTION

Emissieklasse: Stage IV

For sale:

Komatsu PC170 LC-11
Year: 2007
Hours: 5.731
Operating weight: 18.400 kg

Engine:
Komatsu SAA4D107E
Turbo diesel
Power: 90 kW / 121 HP
Cylinders: 4
Displacement: 4.460 cc
Emission: stage IV / Tier 4F

Equipment:
G60 Hydraulic quick coupler
Hammer / sheer / rotation hydraulics
Automatic lubrication

Proportional hydraulics

Cabin:

Air suspension seat

Air conditioning

Rear-view camera

Parking heater

Proportional joysticks

Radio

Undercarriage:

Plate width: 60 cm

Plates condition: 70%

Rolls condition: 50%

Sprocket condition: 70%

Chain condition: 50%

Description:

This Komatsu has sustained damage from a couple falling rocks. There is damage on the upper right side of the machine. All functions are working and there is no structural